



Hondex Front Cover included



Hondex DC power cable - included



NMEA-0183 cables to other instruments Optional



Hondex external GPS antenna GP17H without compass GP17HD with compass recommended



Hondex remote IR or Cabled - optional



Canvas and clear plastic cover Optional

Hondex remote splitter cable for dual wired remotes - optional

Hondex HDX-121 Plotter/Sounder



Cmap Chart SD Card Usually 325 or 320 chart for Maine Coast customers required



Second display, 17-19" AC or DC Optional



USB thumb drive for backup and screen shots - optional



Overhead and bulkhead monitor mount Optional



Dual Channel AIS Receiver Optional



Hondex Transducer 1kw TD47 bronze Thru-hull, 12m cable 1kw TD47M rubber In-hull 12m cable recommended for sounder



Fairing Block for Bronze transducer Recommended



Hondex temperature probe - optional